

Westminster Presbyterian Church Property Condition Assessment

October 18 2021

- High Priority Items (0-18 months)
 - Late 2021 to Early 2023 time-frame
 - General health, safety and code compliance
- Intermediate Term (24 to 36 months)
 - Late 2023 to early 2025
- Long Term (48 months or longer)
 - 2025 to 2029+ time-frame



- High Priority (0-18 months)
 - Protecting the Building Envelope
 - Property Survey (Topo & Utilities) for site designer of comprehensive drainage plan
 - Gutters on the Sanctuary Building
 - Downspouts on the Sanctuary and Education Buildings
 - Drainage/Drainage Matt & Waterproofing
 - Repointing & Mortar Joint Repair
 - Wood Floor Replacement (Education Building)
 - Bell Tower Structural repairs



- High Priority (cont.)
 - Code Items (Electrical)

 Emergency Lighting Interior and Exterior of the - -Sanctuary and Education Buildings)

- Exit Lighting
- Code Items (Mechanical)
 - Boiler Combustion Air Intake
 - Insulation of Piping
 - Toilet Room Exhaust
- Code Items (Site)
 - Handrails and Parking Signs





High Priority Photos



NW Corner of Sanctuary




North Side of Sanctuary



South Wall of Edu Bldg



Wood Floor Damage



Downspouts Discharge Along Blg Foundation



- Intermediate Term (24 to 36 months)
 - Building Interiors and Exterior
 - Window Replacement (Education Bldg.)
 - Basement Shoring (Sanctuary)
 - Window Head and Sill Repair (Edu. Bldg.)
 - Plaster Wall repair (Sanctuary & Edu. Bldg.)
 - Building Ventilation
 - Sanctuary Floor covering



Intermediate Term Photos


















- Long Term (4+ years)
 - Mechanical
 Provide VRF Heating and Cooling system
 to both buildings







Long Term Photos





Approximate Budget by Priority (hard cost)

- High Priority = \$374,000
- Intermediate Term = \$613,000
- Long Term = \$700,000

